




Light Control Function



Hyperfocus









Changing Battery



Warning



Specifications

 1 x AA	 150 m
 10° - 70°	 80 g
 -20°C - +50°C	 IP X4

Additional Information



This manual may contain typographical errors. Data and information are subject to change without notice

Steiner A/S
Dyssen 3
DK-8200 Aarhus N
Phone: +45 87 52 52 12
Fax: +45 87 52 52 15
info@suprabeam.com
www.suprabeam.com

